

EAST Search History

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L2	388	700/180.ccis.	US-PGPUB; USPAT; USOOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/04/29 10:02
S1	3	@ad<"20030227" and ((industry or machine) near3 control\$4) and ((time near2 axis) same (icon or image) same ((size or length) near3 time))	US-PGPUB; USPAT; USOOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/04/28 14:18
S2	118	@ad<"20030227" and ((time near2 axis) same (icon or image) same ((size or length) near3 time))	US-PGPUB; USPAT; USOOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/04/28 14:20
S3	0	@ad<"20030227" and ((time near2 axis) same (icon or image) same ((size or length) near3 time) same (robot or machine))	US-PGPUB; USPAT; USOOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/04/28 14:20
S4	3	@ad<"20030227" and ((industry or machine or robot) near3 control\$4) and ((time near2 axis) same (icon or image) same ((size or length) near3 time))	US-PGPUB; USPAT; USOOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/04/28 14:21
S5	21	@ad<"20030227" and (machine or robot) and ((time near2 axis) same (icon or image) same ((size or length) near3 time))	US-PGPUB; USPAT; USOOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/04/28 14:22
S6	0	@ad<"20030227" and (machining with robot) and ((time near2 axis) same (icon or image) same ((size or length) near3 time))	US-PGPUB; USPAT; USOOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/04/28 14:22

S7	0	@ad<"20030227" and (machining) and ((time near2 axis) same (icon or image) same ((size or length) near3 time))	US-PGPUB; USPAT; USOOR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/04/28 14:22
S8	16597	@ad<"20030227" and (machin\$3 with robot\$3)	US-PGPUB; USPAT; USOOR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/04/28 14:23
S9	186721	@ad<"20030227" and (machin\$3 with (robot\$3 or automat\$3))	US-PGPUB; USPAT; USOOR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/04/28 14:24
S10	8638	@ad<"20030227" and (machining with (robot\$3 or automat\$3))	US-PGPUB; USPAT; USOOR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/04/28 14:24
S11	115	@ad<"20030227" and (machining with (robot\$3 or automat\$3)) and (time near2 axis)	US-PGPUB; USPAT; USOOR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/04/28 14:24
S12	2	@ad<"20030227" and (machining with (robot\$3 or automat\$3)) and ((time near2 axis) same (icon or image))	US-PGPUB; USPAT; USOOR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/04/28 14:24
S13	4	@ad<"20030227" and (machining with (robot\$3 or automat\$3)) and ((time near2 axis) same ((size or length) with (time or period)))	US-PGPUB; USPAT; USOOR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/04/28 14:28
S14	1	@ad<"20030227" and (machining with (robot\$3 or automat\$3)) and ((time near2 axis) same graphic\$3)	US-PGPUB; USPAT; USOOR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/04/28 14:29

S15	19	@ad<"20030227" and (machining with (robot\$3 or automat\$3)) and ((time with axis) same (graphics\$3 or graph))	US-PGPUB; USPAT; USOOR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/04/28 14:34
S16	2	@ad<"20030227" and (machining with (robot\$3 or automat\$3)) and ((time with axis) same (graphic\$3 or graph) same (icon or image))	US-PGPUB; USPAT; USOOR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/04/28 14:34
S17	5	@ad<"20030227" and (machining with (robot\$3 or automat\$3)) and (time with (graphics\$3 or graph) with (icon or image))	US-PGPUB; USPAT; USOOR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/04/28 14:37
S18	0	@ad<"20030227" and (machining with (robot\$3 or automat\$3)) and ((graphic\$3 or graph) with path with (icon or image))	US-PGPUB; USPAT; USOOR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/04/28 14:42
S19	8638	@ad<"20030227" and (machining with (robot\$3 or automat\$3))	US-PGPUB; USPAT; USOOR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/04/28 14:42
S20	225724	@ad<"20030227" and (machining)	US-PGPUB; USPAT; USOOR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/04/28 14:43
S21	3161	@ad<"20030227" and (machining) and (graph \$4 with represent\$5)	US-PGPUB; USPAT; USOOR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/04/28 14:43
S22	198	@ad<"20030227" and (machining) and (graph \$4 with represent\$5 with (path or tool))	US-PGPUB; USPAT; USOOR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/04/28 14:44

S23	14	@ad<"20030227" and (machining) and (graph \$4 with represent\$5 with (path or tool) with axis)	US_PGPUB; USPAT; USOOR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/04/28 14:44
S24	105	@ad<"20030227" and (task with time with icon)	US_PGPUB; USPAT; USOOR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/04/28 19:30
S25	1	@ad<"20030227" and (task with time with icon with axis)	US_PGPUB; USPAT; USOOR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/04/28 19:30
S26	1	@ad<"20030227" and ((task or job) with time with icon with axis)	US_PGPUB; USPAT; USOOR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/04/28 19:31
S27	5	@ad<"20030227" and ((task or job) with icon with axis)	US_PGPUB; USPAT; USOOR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/04/28 19:32
S28	1	@ad<"20030227" and "700"/\$_.cls. and (icon with timeline)	US_PGPUB; USPAT; USOOR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/04/28 19:33
S29	114	@ad<"20030227" and (icon with timeline)	US_PGPUB; USPAT; USOOR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/04/28 19:34
S30	3	@ad<"20030227" and (icon with timeline with (task or job or procedure))	US_PGPUB; USPAT; USOOR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/04/28 19:34

4/ 29/ 2008 10:05:41 AM

C:\ Documents and Settings\jshepard\ My Documents\ EAST\ Workspaces\ machine_10789420.wsp